B.R. No: 329/13-14, Date: 31/08/2013

Name of work : Desilting of SWD drain at Kammgondanahalli near Jarakabande kaval slum Primary drain in Ward no. 12, in SSD

Chief Engineer
Dasarahalli Zone
BBMP, Bangalore

Inspection Report

Name of Work	:	Desilting of SWD drain at Kammgondanahalli near Jarakabande kaval slum Primary drain in Ward no. 12, in SSD.
Work Order	:	No. EE/DD/WO/93/11-12, Dated: 05/08/2011
Agency	:	Rajrajeshwari Construction
B.R. No & Dated	:	329/13-14, Date: 31/08/2013
Bill Amount	:	Rs. 1005870/-
Job Code	:	012-12-000015
P. Code	:	P-0546

The Location is inspected by me alongwith concerned Engineers, and ascertained that as the work is executed as shown in the photo's enclosed.